













Ersatzteile MK 930 rahmenlos mit Wandwinkel

<p>Drehtür Frontseitenwand Typ 5610/5611 Typ 5612/5613</p> 		PK 1227	O-Dichtung	L = 2500 mm	9800 080 545 099	36,99 € Stück
		2x PK 1306	Magnetprofil	L = 2500 mm	9800 080 137 099	56,99 € / Paar
		PK 1501 PK 627	Spritzschutz Einschubdichtung 14,5 mm	L = 1000 mm	9800 080 546 099	30,99 € / Stück
		2x PK 1306 1x PK 1501 1x PK 627 1x PK 1227	kompletter Dichtungssatz		9801 080 048 099	102,99 € / Set

<p>Drehtür für Nische Typen 5610/5611 5612/5678</p> 		PK 1227	O-Dichtung	L = 2500 mm	9800 080 545 099	36,99 € Stück
		PK 1306 PK 1229	Magnetprofil	L = 2500 mm	9800 080 684 099	56,99 € / Paar
		PK 1501 PK 627	Spritzschutz Einschubdichtung 14,5 mm	L = 1000 mm	9800 080 546 099	30,99 € / Stück
		1x PK 1306 1x PK 1227 1x PK 1501+627 1x PK 1229	Dichtungssatz		9801 080 049 099	102,99 € / Set

<p>EckEinstieg Drehtüren Typ 5618</p> 		2 x PK 1227	O-Dichtung	L = 2500 mm	9800 080 547 099	56,99 € / Paar
		PK 1304 PK 1305	Magnetdichtung	L = 2500 mm	9800 080 128 099	56,99 € / Paar
		2 x PK 1501 2 x PK 627	Spritzschutz Einschubdichtung 14,5 mm	L = 1000 mm	9800 005 555 099	41,99 € / Stück
		1x PK 1304 1xPK 1305 2x PK 1501 2xPK 627 2x PK 1227	kompletter Dichtungssatz		9801 080 050 099	102,99 € / Set